




Operating Instructions 使用说明



English	⚠ DANGER		CAUTION
	Read and understand these instructions before installing, operating, or maintaining the equipment.	 Hazardous voltage. Will cause death or serious injury. Turn off and lock out all power supplying this device before working on this device.	Reliable functioning of the equipment is only ensured with certified components.
中文	⚠ 危险		小心
	安装、使用和维修本设备前必须先阅读并理解本说明。	 危险电压。 可能导致生命危险或重伤危险。 操作设备时必须确保切断电源。	只有使用经过认证的部件才能保证设备的正常运转。

Technical Hotline: Telephone: +86-400-810-4288 (8:30 - 17:15 UTC+8) Fax: ++86-10-6471-9991
E-mail: 4008104288.cn@siemens.com
Internet: www.4008104288.com.cn or www.ad.siemens.com.cn/service


Mounted on contactor / 插接安装




Stand-alone mounted / 独立安装




● for stand-alone mounted
▼ for mounted on contactor



Setting / 设置




	TEST	STOP	RESET
NC 95 96			
NO 97 98			

NO / NC		L1, L2, L3 T1, T2, T3	3RU5156 M8	3RU5156 / M10 170 ... 205 A
 Ø 5 ... 6 mm / PZ2	0,8 ... 1,2 Nm 7 to 10.3 lbf-in		10 ... 14 Nm 89 to 124 lbf-in	14 ... 20 Nm 124 to 178 lbf-in
	2 x 0,5 ... 1,5 mm ² 2 x 0,75 ... 2,5 mm ²		—	—
	2 x 0,5 ... 2,5 mm ²		—	—
—	—		2 x 20 x 3 mm M8 x 25/10 ... 14 Nm	—
—	—		2 x 50 ... 120 mm ²	1 x 150 mm ²
AWG	2 x 18 to 14	AWG	2 x 1/0 to MCM	—


Circuit diagrams

电路图




Mounting position

安装位置



Dimension drawings





尺寸图



Accessory Assembly

附件安装

S6



3RU5956-5AA01

3RU5956-3AA01

